


The image shows a long, multi-colored sound barrier wall (green, white, and red) running alongside a railway track. In the foreground, a large, dense bush of sunflowers with bright yellow flowers and large green leaves is growing against the wall. To the right of the sunflowers, there is a patch of green grass and some smaller flowering plants. In the background, overhead power lines and a tall metal structure are visible against a blue sky with some clouds.

Vorstellung der Schallschutzwände Bornheim / Alfter

DB Netz AG, Lärmsanierung
Hermann-Pünder-Str. 3, 50679 Köln

Lärmsanierung an vorhandenen Schienenwegen des Bundes



Lärmsanierung an vorhandenen Schienenwegen des Bundes



**Einbau der Rammrohre
mit Vibrationsramme
am Zweiwegebagger**



Lärmsanierung an vorhandenen Schienenwegen des Bundes



Einbau der Rammrohre

Lärmsanierung an vorhandenen Schienenwegen des Bundes



**Einbetonieren der Stützen
in die Rammrohre**

Lärmsanierung an vorhandenen Schienenwegen des Bundes



**Einbau der Sockel-
Elemente**

Lärmsanierung an vorhandenen Schienenwegen des Bundes



Einbau der Alu-Elemente



Lärmsanierung an vorhandenen Schienenwegen des Bundes

